

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11798

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080055-3

RECEIVED FROM

DATE REC'D. 4-4-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
	DRAWING NO. AND DESCRIPTION						QUANTITY			
2	322		007	0	10					
	731603 Motor Intervalometer						2			
	IPS #05317									

RECEIVED
BYINSPECTED
BY

DATE

RECEIPTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11800

2761 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 4-4-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
	DRAWING NO. AND DESCRIPTION						QUANTITY			
1	322		143	0	10					
	731655 Motor Intervalometer						1			
	IPS #05316									

RECEIVED
BY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080055-3